

TABLA DE SÍMBOLOS EMPLEADOS EN MANEJO DE PIEZAS

Handling symbols  
in accordance with VDI 2860

- 1 Handling (basic symbol)
- 2 Orderly storage (magazing)
- 3 Random storage (hoppers)
- 4 Semi-orderly storage (stacking)
- 5 Branching
- 6 Combining
- 7 Clamping
- 8 Unclamping
- 9 Holding (without force action)
- 10 Turning
- 11 Swivelling
- 12 Distribution (of n workpieces)
- 13 Positioning
- 14 Sliding
- 15 Sorting
- 16 Forwarding
- 17 Guiding (whilst maintaining work-piece orientation at all times)
- 18 Testing
- 19 Production process (basic symbol)
- 20 Shape changing (shaping, cutting)
- 21 Treatment (coating, modification of material properties)
- 22 Joining (assembly)
- 23 Shape changing (creative forming)
- 24 Checking (basic symbol)

